

Humidity

No.	Quantity, Measuring Instrument, Material Measure	Range	Best Measurement Capability lab(\pm)
1	Humidity Chamber	10 to 75% RH	0.70% RH
		75 to 95% RH	1.01% RH
2	Environmental Humidity Meter	10 to 95% RH	$(0.7+0.003H)\%$ RH, H(%RH)