

Pressure

No.	Quantity, Measuring Instrument, Material Measure	Range	<i>Best Measurement Capability lab(±)</i>	
1	Vacuum Gauge	-0.8 to 0 bar	0.06% Fs	
2	Elastic Sensing Elements Pressure Gauges	Pneumatic	Up to 20 bar	0.06% Fs
		Hydraulic	Up to 700 bar	0.011% rdg
3	Electromechanical Pressure Gauges (Transmitter & Transducer)	Pneumatic	Up to 20 bar	0.06% Fs
		Hydraulic	Up to 700 bar	0.025% rdg
4	Pressure Recorders	Pneumatic	Up to 20 bar	0.06% Fs
		Hydraulic	Up to 700 bar	0.011% rdg
5	Pressure Switch	Pneumatic	Up to 20 bar	0.06% Fs
		Hydraulic	Up to 700 bar	0.025% rdg
6	Safety Valve Operation Test	Pneumatic	Up to 20 bar	0.06% Fs